

New Product Update

Cycle Pro is proud to announce available for immediate shipment 3 new Extremely popular Sensors for the V-Twin market

Selling points:

Direct Replacement to OEM

All sensors 100% tested

In-Stock for fast shipping

Highest Quality Replacement Parts Available.



CP# 18430 MAP Sensor

Replaces OEM# 32316-99, 32424-99, 32424-98, 32416-10, 32417-10.

Early style MAP sensor fits approx. 88 applications, we can supply complete application list many models.

Suggested Shop Price \$32.95

Retail \$69.95

CP# 18431 MAP Sensor (Late design)

Replaces OEM# 32319-07 and 32319-07A

Early style MAP sensor fits approx. 67 applications, we can supply complete application list many models.

Suggested Shop Price \$34.95

Retail \$79.95



CP# 18440 IAC Motor (Valve)

Replaces OEM# 27658-06

IAC Motor (Valve) fits approx. 126 applications, we can supply complete application list many models.

Suggested Shop Price \$36.75

Retail \$59.95

Cycle Pro® has 100% coverage of O2 Sensors for the V-Twin market

Harley Davidson Applications:

CP# 14272 replaces OEM # 27719-07
CP# 14273 replaces OEM # 27683-07
CP# 14274 replaces OEM # 27703-08
CP# 14275 replaces OEM # 27729-10
CP# 14276 replaces OEM # 27809-10
CP# 14278 replaces OEM # 32700005
CP# 14279 replaces OEM # 32700006
CP# 14280 replaces OEM # 32700026
CP # 14281 replaces OEM # 27690-08

- **Cycle Pro®** Oxygen Sensors are precision made for outstanding performance.
- *Direct Fit, No Modifications Needed.*
- *Extra High temperature Dual Shield End*
- *Improved Engine Performance*
- *Best Consolidation—Fewer SKU's for More coverage*
- *ISO 9001 and TS 16949 Certified Manufacturing Plant*

