


## New Product Update

4/20

These kits are designed to include all the components you need to repair and upgrade the Cam Chest of Harley Davidson Twin Cam® Engines.

Our tension Shoes have been upgraded to a more durable Torelon® material for longer life than OEM



### Mechanical Service Kit

**CP # 1254**

#### Twin Cam Tensioner Service Kit

1999-06 except 2006 Dyna.

Includes;


2 Primary Tensioners Early Style

1 Secondary Chain Tensioner

Cam Service Gasket Kit

Tech Sheet

PKG- Kit



### Hydraulic Service Kit

**CP # 1255**

#### Twin Cam Tensioner Service Kit

2007-Up including 2006 Dyna.

Includes;

2 Primary Tensioners Late Style

1 Secondary Chain Tensioner

Cam Service Gasket Kit

Tech Sheet

PKG- Kit

[www.Cycleprollc.com](http://www.Cycleprollc.com)

**Cycle Pro llc**

**261A Rolling Hill Rd**

**Mooresville, NC 28117 USA**

Phone: 704.662.6682

Fax: 704.662.8752


Email: [Thom@Cycleprollc.com](mailto:Thom@Cycleprollc.com)




*Cycle Pro is proud to announce immediate availability of High Performance Cam Change Gasket Kits*

## High Performance Harley Cam Change Gasket Kits


Cam Change Kits with Fomat Gaskets	
Description	CP #
Sportster® 1990-03	8553
Sportster® 2004-19	8554
EVO Big Twin® 1982-91	8551
EVO Big Twin® 1992-99	8552
Twin Cam® All Years	8550
Milwaukee 8® 2017-Up	8549




Sportster® 1990-03




EVO Big Twin® 1982-91




Twin Cam® All Years



Sportster® 2004-19



EVO Big Twin® 1992-99



Milwaukee 8 ® All Years